

FIG. 1
CONVENTIONAL ART




FIG. 2
CONVENTIONAL ART




FIG. 3
CONVENTIONAL ART




FIG. 4
CONVENTIONAL ART




FIG. 5





FIG. 6



This diagram shows a cross-sectional view of a mechanical assembly. A central horizontal component, labeled 30, is shown with a large arrow pointing to the left, indicating its direction of movement. This component is flanked by two parallel horizontal bars, 54 (top) and 60 (bottom), which are secured by a vertical clamping member 70. The clamping member 70 has a central section 80 with a hole 38. A curved, semi-circular component 90 is positioned on the left side of the assembly, with dashed lines and arrows indicating its curved path of motion. A small star symbol 51 is located on the central component 30. The entire assembly is supported by a base structure 34.